

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated

It is certified that the existing building

(name of the

building or premises) at

(address) is having block(s)/Floor(s) as per details below.

Details of block(s) in School	Block 1 (Old School Block)	Block 2 (New Building)	Block 3 Riddhi	Block 4 Siddhi	Block 5 Arney Hall	Block 6 Srushti	Block 7 (Quarters)
No. of Floor(s) in Block	G+1	G+1	G+1	G+1	G	G+1	25


The Building is owned/occupied by Deepshikha Gurukul Sainik School Chikhaldara (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 10/06/2025 (date of inspection) in the presence of Director, Principal. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 10/06/2025 for a period of 15 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. No additional/ alteration or expansion and modifications to this building is to be carried out but without permission of the undersigned.
- 2.
- 3.
- 4.

Issued on 10/06/2025 at Chikhaldara/ Achalpur by Sub divisional engineer and executive engineer respectively.

- Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Eng. Chaudhary

  
SUB DIVISIONAL ENGINEER  
P.W.D. SUB-DIVISION  
CHIKHALDARA

Signature with Seal

Name Eng. Wankhade

Designation Executive  
Engineer

Name & Address of Department/ Office•